

Corrigendum to ECE R 36

Transmitted by the expert from Germany

Para: 5.6.4.9, correct to read: The service door in any open position shall not obstruct
the use of required access to any **mandatory** exit

Justification:

This text was agreed by GRSG on its seventy-sixth session (19 - 23 April 1999) but "mandatory"
was omitted during transmission to W.29