

Proposal for corrigendum to ECE/TRANS/WP.29/GRSG/2022/6


Submitted by the experts of the IWG on VRU-Proxi

The text reproduced below was prepared by the experts of IWG VRU-Proxi. The modifications to the current text of ECE/TRANS/WP.29/GRSG/2022/6 are marked in bold characters and strikethrough for deleted characters.

I. Proposal


Paragraph 15.3., Figure 4 amend to replace:

Figure 4
Field of Detection



Annex 12 Paragraph 1.3.1., Figure 1 amend to read and replace:

Figure 1
~~Figure Title~~ **Field of detection**



Annex 12 Paragraph 1.3.1.1., amend to read:

Figure 2
~~Figure Title~~ **Field of detection of front area**

Annex 12 Paragraph 1.3.1.2., amend to read:

Figure 3
~~Figure Title~~ **Field of detection of corner areas**

Annex 12 Paragraph 1.3.1.3., amend to read:

Figure 4

~~Figure Title~~ Field of detection of side areas

II. Justification

Paragraph 15.3. Figure 4 and Annex 12 Paragraph 1.3.1., Figure 1

Figures used in ECE/TRANS/WP.29/GRSG/2022/6 were only focused on the front area for detection. These figures shall be replaced to the figures focused on detection area all around the vehicle front and lateral side.

Annex 12 Paragraph 1.3.1., Figure 1 to 4

Figure titles in ECE/TRANS/WP.29/GRSG/2022/6 were added.